HYUNDAI – Fly Wheel

November 2006

Target And Remove Rust

Side A – "Front"
Before / After Rust Removal Comparison

This picture sequence provides detailed before and after rust removal comparisons for a Fly Wheel that was processed at Cetex Industries, during November 2006 using Cetex Industries "Rust Ranger" proprietary "84-4C" Rust Removal Compound by Dip- Soak Method.

The Fly Wheel was coated with RD – 4100 Light Oil Film Rust Deterrent, and packaged in a polyethylene sealed bag; to provide Rust Deterrence.

Before / After Rust Removal (Compare Top To Bottom Picture)

Side A – "Front" | **Side B – "Back"**

Packaging