

Allison Transmission – Torque Converter Impeller

June 1999

Before /After Rust Removal



Target And Remove Rust

742 – 34 - 7



This picture sequence provides detailed before and after rust removal comparisons for a lot quantity of Torque Converter Impellers; that were processed at Cetex Industries, during June 1999 using Cetex Industries "Rust Ranger" proprietary "84-4C" Rust Removal Compound with Cetex Industries proprietary processes and processing equipment.

The Impellers were not taken apart and were processed by Cetex's Dip-Soak Method.

After processing the Impellers were coated with RD – 4000 Dry Film Rust Deterrent; to provide Rust Deterrence

