

Bobcat

Ingersoll Rand

Hydraulic Motors (Open-Air Method)


March 2007

1385 - 3 -185



Target and Remove Rust

Before /After Rust Removal



This picture sequence provides detailed before and after rust removal comparisons for a lot quantity Hydraulic Motors. These items were processed by Open-Air Method during March 2007.

The Hydraulic Motors were not taken apart during processing and were coated with RD-4100 Light Oil Film Rust Deterrent, to provided Rust Deterrence during shipment and storage.

Hydraulic Motors were not taken apart during Rust Removal Processing

As Received - Packaging



As Shipped - Packaging

