

AGCO – Axle Housing

October 2006

Before /After Rust Removal




Target And Remove Rust

5 – 418 – 67



This picture sequence provides detailed before and after rust removal comparisons for an Axle Housing; that was processed at Cetex Industries, during October 2005; using Cetex Industries “Rust Ranger” proprietary “84-4C” Rust Removal Compound with Cetex Industries proprietary processes and processing equipment.



The part was not taken apart during processing, and did not require specific special handling requirements; and was processed by Dip-Soak Method.

After processing items was coated inside and out with RD – 4000 Dry Film Rust Deterrent.