

Questcor – Conveyor Roller

November 2006



Before / After Rust Removal Comparison



This picture sequence provides detailed before and after rust removal comparisons for a Conveyor Roller that was processed at Cetex Industries, during November 2006 using Cetex Industries "Rust Ranger" proprietary "84-4C" Rust Removal Compound by Dip-Soak Method.

The Roller Conveyor was coated with RD – 4100 Light Oil Film Rust Deterrent, to provide Rust Deterrence.