

# Hyundai - Piston

November 2006



Target And Remove Rust

## Rust Removal Picture Detail

Before

After



This picture sequence provides detailed before and after rust removal comparisons for a Piston that was processed at Cetex Industries, during November 2006 using Cetex Industries "Rust Ranger" proprietary "84-4C" Rust Removal Compound by Dip- Soak Method.

The Piston was coated with RD - 4100 Light Oil Film Rust Deterrent, and packaged in a polyethylene sealed bag; to provide Rust Deterrence.

