

# HYUNDAI – Shaft Collar

November 2006



## Before / After Rust Removal Comparison



This picture sequence provides detailed before and after rust removal comparisons for a Shaft Collar that was processed at Cetex Industries, during November 2006 using Cetex Industries "Rust Ranger" proprietary "84-4C" Rust Removal Compound by Dip- Soak Method.

The Support was coated with RD – 4100 Light Oil Film Rust Deterrent, and packaged in a polyethylene sealed bag; to provide Rust Deterrence.