

HYUNDAI – Support

November 2006



Side A – “Front” Before / After Rust Removal Comparison



This picture sequence provides detailed before and after rust removal comparisons for a Support that was processed at Cetex Industries, during November 2006 using Cetex Industries “Rust Ranger” proprietary “84-4C” Rust Removal Compound by Dip- Soak Method.

The Support was coated with RD – 4100 Light Oil Film Rust Deterrent, and packaged in a polyethylene sealed bag, to provide Rust Deterrence.

Before / After Rust Removal (Compare Top To Bottom Picture) Side A – “Front” Side B – “Back”



Packaging

