


# AGCO – Pivot Boom

June 2006



Target And Remove Rust

6 – 712 - 64

This picture sequence provides detailed before and after rust removal comparisons for Pivot Booms; that were processed at Cetex Industries, during June 2005; using Cetex Industries “Rust Ranger” proprietary “84-4C” Rust Removal Compound with Cetex Industries proprietary processes and processing equipment.

The part was not taken apart during processing, and did not require specific special handling requirements; and was processed by Dip-Soak Method.

After processing items was coated inside and out with RD – 4000 Dry Film Rust Deterrent.

