




CNH – Skid Steer Housing

June 2003



Target And Remove Rust

Before / After Rust Removal Comparison



This picture sequence provides detailed before and after rust removal comparisons for a Skid Steer Housing that was processed at Cetex Industries, during June 2003; using Cetex Industries “Rust Ranger” proprietary “84-4C” Rust Removal Compound by Dip- Soak Method.

The Housing was coated with RD – 4100 Light Oil Film Rust Deterrent, to provide Rust Deterrence.